




Tools & Supplies Needed

- Band Saw or Coping Saw
- Electric hand drill or press
- #44 Drill Bit
- Sharp Pointed Object (punch)
- 1/4" Tungsten Cubes or...
- Plate for weight
- Body Putty / Wood Filler
- Safety Glasses
- Hearing Protection
- Scissors
- Markers
- Sandpaper
- Paint

For 1/4" Tungsten Cubes [CLICK HERE](#)



WWW.DERBYMONKEYGARAGE.COM

All works in these plans including text and graphics are sole property of Derby Monkey Garage. Reproduction and/or redistribution are prohibited.